



Table 3: Site photographs.



Figure 2: View of the access road from the northeast to the entrance of the Savuka 5a & 5b and Savuka 7a & 7b TSFs.



Figure 3: View of the access road to the Savuka 7a & 7b TSFs from the Savuka 5a&5b TSFs towards the south-west (road northeast of the 7a & 7b TSFs).



Figure 4: View of the northeastern corner of the Savuka 7a & 7b TSFs.



Figure 5: View of the road on the Savuka 7a&7b TSFs to the north.



Figure 6: View of the side slope of the top of the Savuka 7a & 7b TSFs to the north



Figure 7: View of the adjacent land uses to the northwest of the study area.



Figure 8: View of the northern part of the stormwater dam and return dam overflow from the top of the TSFs.



Figure 9: View of the return water dam and the southern part of the stormwater dam and return dam overflow from the top of the TSFs.



Figure 10: View of the road on the TSF to the west of the study area.



Figure 11: View of the road on top of the TSF between the Savuka 7a & 7b TSFs, looking east.



Figure 12: View of the road and the top of the TSFs between the Savuka 7a & 7b TSFs, looking east.



Figure 13: View from the road on the TSFs to the south of the study area towards the west. The netting for dust mitigation is visible in the foreground on the side slopes and the existing plantation for phytoremediation in the background.



Figure 14: View from the road on the TSFs to the south of the study area towards the south. The netting for dust mitigation is visible in the foreground on the side slopes of the TSFs.



Figure 15: View from the road on the TSFs to the south of the study area towards the east. The netting for dust mitigation is visible in the foreground on the side slopes of the TSFs.



Figure 16: Vegetation on the side slopes of the TSFs.



Figure 17: Vegetation on the side slopes of the TSFs. Photograph taken from the upper road of the TSFs to the south-east of the TSFs.



Figure 18: View of the valley between the Savuka 7a & 7b and the Savuka 5a& 5b TSFs towards the east.



Figure 19: View of the valley between the Savuka 7a & 7b and the Savuka 5a& 5b TSFs towards the north-east. The Savuka 5a&5b TSFs can be seen in the background across the valley.



Figure 20: View of the valley between the Savuka 7a & 7b and the Savuka 5a& 5b TSFs towards the north. The Savuka 5a&5b TSFs can be seen in the background across the valley.



Figure 21: Vegetation on the side slopes of the TSFs. Photograph taken from the upper road of the TSFs to the east of the TSFs towards the north.